

# WEI<sup>1</sup> LOG AND DRILLING REPORT

NO CARBON PAPER  
NECESSARY -  
SELF-TRANSCRIBING

State of Ohio  
DEPARTMENT OF NATURAL RESOURCES  
Division of Water  
Fountain Square  
Columbus, Ohio 43224

598452

COUNTY Summit TOWNSHIP Franklin SECTION OF TOWNSHIP \_\_\_\_\_  
OWNER Dick Brigergrain ADDRESS 217 W Nimisila Rd.  
LOCATION OF PROPERTY West Nimisila Rd. approx. 44319

## CONSTRUCTION DETAILS

## BAILING OR PUMPING TEST (specify one by circling)

Casing diameter 5" Length of casing 39 ft 2" Test rate 15 gpm Duration of test 1 hrs  
Type of screen \_\_\_\_\_ Length of screen 1 Drawdown 18 ft Date June 23 - 82  
Type of pump \_\_\_\_\_ Static level (depth to water) 9 ft  
Capacity of pump \_\_\_\_\_ Quality (clear) cloudy, taste, odor) \_\_\_\_\_  
Depth of pump setting \_\_\_\_\_ Pump installed by \_\_\_\_\_  
Date of completion June 23 1982

## WELL LOG\*

## SKETCH SHOWING LOCATION

Formations: sandstone, shale,  
limestone, gravel, clay

From

To

Locate in reference to numbered  
state highways, street intersections, county roads, etc.

0 ft

ft

Gravel & Clay 0 12  
Clay 12 38  
Sandy Shale 38 43

W

West Nimisila

E

water at 40 ft

N

S

DRILLING FIRM Hensel Well Drilling  
ADDRESS 1388 W Nimisila Rd.

DATE June 23 - 1982  
SIGNED Renner Hensel

\*If additional space is needed to complete well log, use next consecutive numbered form.

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224

2726