

599178

COUNTY Wayne TOWNSHIP Baughman SECTION OF TOWNSHIP 13
OWNER Russell C. Koppes ADDRESS 5617 Deerfield Ave. N.W. ^{NORTH LAWRENCE}
LOCATION OF PROPERTY 5617 Deerfield Ave. N.W. N. Lawrence

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST
(specify one by circling)

Casing diameter 5" Length of casing 130'
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

Test rate 10 gpm Duration of test 2 hrs
Drawdown 40' ft Date Sept 20, 1982
Static level (depth to water) 35' ft
Quality (clear, cloudy, taste, odor) cloudy
Pump installed by _____

WELL LOG*

SKETCH SHOWING LOCATION

Formations: sandstone, shale,
limestone, gravel, clay

From

To

Locate in reference to numbered
state highways, street intersections, county roads, etc.

Yellow Clay	0 ft	20 ft
Blue Clay Sand-gravel	20	128
Shale	128	136
Sandstone	136	150

water found in Sandstone		
at 145'		

Wayne Co

Arcadia St

RT 21

N

S

W

E

DRILLING FIRM Wharton Neal well Drilling

DATE Sept 21, 1982

ADDRESS 549 S. Canal St. Canal Fulton, Ohio

SIGNED Quentin Neal

• If additional space is needed to complete well log, use next consecutive numbered form.

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224