

WELL LOG AND DRILLING REPORT

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

599183

COUNTY Stark TOWNSHIP Lawrence SECTION OF TOWNSHIP _____
OWNER Pat Waters ADDRESS 8331 Manchester Ave. N.W. Canal Fulton Oh.
LOCATION OF PROPERTY 8601 Erie Ave N.W. Canal Fulton Oh. 44614

CONSTRUCTION DETAILS

Casing diameter 5" Length of casing 166'
Type of screen bro p Length of screen 6
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST

(specify one by circling)

Test rate 15 gpm Duration of test 5 hrs
Drawdown 15' ft Date June 20-83
Static level (depth to water) 30' ft
Quality (clear, cloudy, taste, odor) clear
Pump installed by _____

WELL LOG*

Formations: sandstone, shale,
limestone, gravel, clay

From


To

Yellow clay sand & gravel	0 ft	15 ft
Blue clay	15	15.5
Sand-gravel	15.5	166

water at 166'

SKETCH SHOWING LOCATION

Locate in reference to numbered
state highways, street intersections, county roads, etc.



DRILLING FIRM Quentin Neal well drilling

DATE June 27, 1983

ADDRESS 5485 Canal St. Canal Fulton Oh.

SIGNED Quentin Neal

*If additional space is needed to complete well log, use next consecutive numbered form.

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224