

WELL LOG AND DRILLING REPORT

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

599475

COUNTY SENECA TOWNSHIP LOU DON SECTION OF TOWNSHIP 15
OWNER DAVE REES KREASIS ADDRESS 9025 W STATE RT 18
LOCATION OF PROPERTY ON 18 5TH HOUSE N SCHULTZ RD N. SIDE FOSTORIA

CONSTRUCTION DETAILS

Casing diameter 5 1/8 Length of casing 54
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

(BAILING OR PUMPING TEST (specify one by circling))

Test rate 20 gpm Duration of test 1 hrs
Drawdown -0- ft Date 1-30-85
Static level (depth to water) 23 ft
Quality (clear, cloudy, taste, odor) CLEAR
Pump installed by _____

WELL LOG*

Formations: sandstone, shale,
limestone, gravel, clay


From

To

CLAY	0 ft	40 ft
SAND	40	43
CLAY	43	48
LIMESTONE	48	85

SKETCH SHOWING LOCATION

Locate in reference to numbered
state highways, street intersections, county roads, etc.



DRILLING FIRM PARMENTER DRILLING CO DATE 2-12-85
ADDRESS 631 N. MAIN FOSTORIA, OH SIGNED [Signature]

*If additional space is needed to complete well log, use next consecutive numbered form.

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224