WELL LOG AND DRILLING REPORT

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

NO CARBON PAPER NECESSARY– SELF-TRANSCRIBING

599847

Well No. 1 Pumping sand would not clear up.

COUNTY Madison TOWNSHIP Pleasant SECTION OF TOWNSHIP

OWNER William Graham ADDRESS 10239 Kiousville Palestine Rd

LOCATION OF PROPERTY Kiousville-Palestine Mt. Sterling Ohio 43143

CONSTRUCTION DETAILS

Casing diameter 6 1/4 ID 44 ID Length of casing 215' 133'

Type of screen Length of screen Double Cased

Type of pump

Capacity of pump

Depth of pump setting

Date of completion

BAILING OR PUMPING TEST
(specify one by circling)

Test rate gpm Duration of test hrs

Drawdown ft Date

Static level (depth to water) ft

Quality (clear, cloudy, taste, odor)

Pump installed by

WELL LOG*

Formations: sandstone, shale, limestone, gravel, clay	From	To
Blue Clay	0 ft	30 ft
Blue plastic type Clay	30	90
Sand	90	97
Blue gumbo	97	348
Limestone	348	373
This well is double cased		
Water would not clear up		
G.P.M very low		

SKETCH SHOWING LOCATION

Locate in reference to numbered state highways, street intersections, county roads, etc.



DRILLING FIRM Plains Drilling Co. DATE 5-21-84

ADDRESS Rt. 4 London Ohio SIGNED Fred C. Blake

*If additional space is needed to complete well log, use next consecutive numbered form.

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224