

WELL LOG AND DRILLING REPORT

NO CARBON PAPER
NECESSARY-
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

600866

COUNTY LORAIN TOWNSHIP AVON SECTION OF TOWNSHIP _____
OWNER DAN SHAW ADDRESS 810 CONCORD AVE ELYRIA
LOCATION OF PROPERTY 36428 MILLS Rd 1/4 MILE WEST OF RT 83

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST (specify one by circling)

Casing diameter 5 Length of casing 25
Type of screen - Length of screen _____
Type of pump SUBMERSIBLE
Capacity of pump 8 GPM
Depth of pump setting 45'
Date of completion 8-23-82

Test rate 15 gpm Duration of test 1 hrs
Drawdown 40 ft Date 8-17-82
Static level (depth to water) 6 ft
Quality (clear, cloudy, taste, odor) CLEARING
NO ODOOR
Pump installed by BERN SCHUSTER

WELL LOG*

SKETCH SHOWING LOCATION

Formations: sandstone, shale,
limestone, gravel, clay

From

To

Locate in reference to numbered
state highways, street intersections, county roads, etc.

CLAY, YELLOW

0 ft

8 ft

" BLUE

8

15

SAND

15

18

SANDSTONE

18

50

WATER IN SANDSTONE

W

N

X

MILLS Rd

E

RT 83

S

DRILLING FIRM BERN SCHUSTER
ADDRESS ELYRIA OHIO

DATE 8-23-82
SIGNED B Schuster

*If additional space is needed to complete well log, use next consecutive numbered form.

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224