

WELL LOG AND DRILLING REPORT

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

600877

COUNTY LORAIN TOWNSHIP ELYRIA SECTION OF TOWNSHIP _____

OWNER ANDREW ONDERKO ADDRESS 7306 MURRAY RIDGE RD

LOCATION OF PROPERTY 7306 MURRAY RIDGE Rd ELVIRA OHIO

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST

(specify one by circling)

Casing diameter 5 1/2 00 Length of casing 25

Test rate 4 gpm Duration of test 1 hrs

Type of screen _____ Length of screen _____

Drawdown 55 ft

Duration of test 1 hrs

Date 5-19-84

Type of pump SUBMERSIBLE

Static level (depth to water) 3 ft

Capacity of pump 4 GPM FLOW VALVE

Quality (clear, cloudy, taste, odor) CLEAR NO ODOR

Depth of pump setting 55

Date of completion.

Pump installed by BORN SCHUSTER
ELECTRIC BY OWNER

WELL LOG*

SKETCH SHOWING LOCATION

Formations: sandstone, shale,
limestone, gravel, clay

From

To

Locate in reference to numbered
state highways, street intersections, county roads, etc.

SURFACE

0 ft

6 ft

BROKEN YELLOW STONE	6	12
---------------------	---	----

LIGHT SANDSTONE	12	60
-----------------	----	----

LIGHT SHALE	60	61
-------------	----	----

WATER IN LIGHT STONE

W

N

E

S

DRILLING FIRM BERN SCHUSTER

DATE MAY 22 84

ADDRESS GLYRIA C.

SIGNED 15 Schwartz

*If additional space is needed to complete well log, use next consecutive numbered form.

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224