

WELL LOG AND DRILLING REPORT

LOCATED

NO. 56 60315

County Preble Township Harrison Section of Township 27
 Owner Chas. Mantel Address Lewisburg, O.
 Location of property 1/4 mi E of Lewisburg 1/4 mi N.

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST

Casing diameter 6" Length of casing 52' Pumping rate _____ G.P.M.
 Type of screen _____ Length of screen _____ Duration of test _____ hrs.
 Type of pump _____ Drawdown _____ ft. Date _____
 Capacity of pump _____ Developed capacity _____
 Depth of pump setting _____ Static level - depth to water 13 ft.
 Date of completion _____ Pump installed by _____

WELL LOG

SKETCH SHOWING LOCATION

Formation

From

To

N.

red clay
br. clay
sand
gravel

0

15

22

50

53

W.

E.

S.

Drilling Firm Ira DullDate 10-1-59

Address _____

Copied by ES

56