

WELL LOG AND DRILLING REPORT

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

603341

COUNTY Summit TOWNSHIP Bath SECTION OF TOWNSHIP SE
OWNER John Ritzic ADDRESS 3720 Paula Dr Richfield Ohio
LOCATION OF PROPERTY 2534 Shade Rd at Bath Rd

CONSTRUCTION DETAILS

Casing diameter 5" Length of casing 205
Type of screen 4" Length of screen 215
Type of pump Supplied by owner
Capacity of pump —
Depth of pump setting —
Date of completion 10-20-82

BAILING OR PUMPING TEST

(specify one by circling)


Test rate 10 gpm Duration of test 1 hrs
Drawdown 80 ft Date 10-20
Static level (depth to water) 119 ft
Quality (clear, cloudy, taste, odor) Clearing
Pump installed by Owner

WELL LOG*

Formations: sandstone, shale, limestone, gravel, clay	From	To
<u>Sandy Clay</u>	<u>0 ft</u>	<u>140 ft</u>
<u>Dirty Sand</u>	<u>140</u>	<u>214</u>
<u>Sand & Gravel</u>	<u>214</u>	<u>215</u>
<u>Water 215</u>		

SKETCH SHOWING LOCATION

Locate in reference to numbered
state highways, street intersections, county roads, etc.



DRILLING FIRM Wersching Well Drilling DATE 10-21-82
ADDRESS Amherst Ohio SIGNED Roy E Wersching

*If additional space is needed to complete well log, use next consecutive numbered form.

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224