

WELL LOG AND DRILLING REPORT

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

604159

COUNTY Crawford TOWNSHIP Holmes SECTION OF TOWNSHIP 4
OWNER Harrell May ADDRESS 5568 SR 19 Bucyrus Ohio
LOCATION OF PROPERTY About 300 ft south intersection county Rd 26 on state Rd 19

CONSTRUCTION DETAILS

Casing diameter 4 1/2 Length of casing 78

Type of screen 2 Length of screen

Type of pump

Capacity of pump

Depth of pump setting

Date of completion

BAILING OR PUMPING TEST
(specify one by circling)

Test rate 5+ gpm Duration of test 1 hrs

Drawdown 1 ft Date Feb 23, 1991

Static level (depth to water) 110 ft

Quality (clear, cloudy, taste, odor) See above

Pump installed by

WELL LOG*

Formations: sandstone, shale,
limestone, gravel, clay

From

To

0 ft	72 ft
------	-------

72	74
----	----

74	744
----	-----

745	128 1/2
-----	---------

SKETCH SHOWING LOCATION

Locate in reference to numbered
state highways, street intersections, county roads, etc.

N

State Health

W

County Rd 26 Broken sword

F

5

DRILLING FIRM**ADDRESS**

DATE _____

SIGNED

* If additional space is needed to complete well log, use next consecutive numbered form.

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224