

WELL LOG AND DRILLING REPORT

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

605651

COUNTY WAYNE TOWNSHIP Milton SECTION OF TOWNSHIP 8
OWNER Roger LANCE ADDRESS HAUFFMAN AVE
LOCATION OF PROPERTY Sterling

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST (specify one by circling)

Casing diameter 5" Length of casing 92
Type of screen NONE Length of screen NONE
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion Feb 18, 1983

Test rate 15 gpm Duration of test 2 hrs
Drawdown 30 ft Date Feb 18, 1983
Static level (depth to water) 30 ft
Quality (clear) cloudy, taste, odor) _____
Pump installed by OWNER ??

WELL LOG*

SKETCH SHOWING LOCATION

Formations: sandstone, shale,
limestone, gravel, clay

From

To

Locate in reference to numbered
state highways, street intersections, county roads, etc.

CLAY

0 ft

70 ft

SAND

70

80

CLAY

80

90

SAND + GRAVEL

90

92

N

Sterling

60 ft 304

W

St Rt 604

E

S

DRILLING FIRM R. A. Hargul & Son
ADDRESS 99 38 Coast Bank Rd

DATE March 1, 1983
SIGNED John Hargul

*If additional space is needed to complete well log, use next consecutive numbered form.

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224 S