

WELL LOG AND DRILLING REPORT

**NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING**

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

606292

COUNTY LUCAS TOWNSHIP SYLVANIA SECTION OF TOWNSHIP _____
OWNER JAMES SULLA DECK ADDRESS 5934 FRIEDLY
LOCATION OF PROPERTY 5934 FRIEDLY

CONSTRUCTION DETAILS

Casing diameter 510 Length of casing 64'
Type of screen NONE Length of screen NONE
Type of pump SUMERSBURY
Capacity of pump 10 PER MIN
Depth of pump setting 60'
Date of completion JUNE 4 - 93

BAILING OR PUMPING TEST
(specify one by circling)

Test rate 1.5 gpm Duration of test 2 hrs
Drawdown 2' ft Date JUNE 2 93
Static level (depth to water) 37' ft
Quality (clear, cloudy, taste, odor) _____
Pump installed by BISCHOFF DRILLING

WELL LOG*

Formations: sandstone, shale,
limestone, gravel, clay

From

To

0 ft

12 ft

12

20

20

40

40

40

50

40

60

fo

SKETCH SHOWING LOCATION

Locate in reference to numbered
state highways, street intersections, county roads, etc.

N

WELL

A hand-drawn map showing a rectangular area. A horizontal line runs across the middle, with 'W' at the left end and 'E' at the right end. A vertical line runs down the left side, labeled 'FLADERS' vertically. Another vertical line runs down the right side, labeled 'TALMADGE' vertically. In the center, above the horizontal line, is a small rectangle labeled 'FRED'S' vertically. Below the horizontal line, in the center, is the name 'ALEXIS'. At the bottom center is the letter 'S'.

DRILLING FIRM

ADDRESS: 8264 WHITEFORD CENTER RD

DATE

SIGNED

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224