

WELL LOG AND DRILLING REPORT

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

606570

COUNTY GREENE TOWNSHIP CEDARVILLE SECTION OF TOWNSHIP EASTERN
OWNER DAVID RUTMAN ADDRESS 2610 HARRISON RD
LOCATION OF PROPERTY 2610 HARRISON RD

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST
(specify one by circling)

(specify one by circling)

Casing diameter 5" Length of casing 28' 2"
Type of screen _____ Length of screen _____
Type of pump SUBMERGIBLE
Capacity of pump 12 GPM
Depth of pump setting 45'
Date of completion 2/6/85

Test rate 12 gpm Duration of test 2 hrs
Drawdown 20 ft Date 2/6/85
Static level (depth to water) 8' ft
Quality (clear, cloudy, taste, odor) CLEAR
Pump installed by Mike Battaglia

WELL LOG*

SKETCH SHOWING LOCATION

Formations: sandstone, shale,
limestone, gravel, clay

From

To

Top Soil	0 ft	1 ft
CLAY	1	6
GRAVEL & SAND	6	10
SAND	10	12
Limestone	12	48

Locate in reference to numbered
state highways, street intersections, county roads, etc.

W

E

DRILLING FIRM HUGHES DRILLING
ADDRESS 2498 HARRISON RD

DATE 3/1/85
SIGNED ME Battaglia

*If additional space is needed to complete well log, use next consecutive numbered form.

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224

43