

WELL LOG AND DRILLING REPORT

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

607859

COUNTY Franklin TOWNSHIP Prairie SECTION OF TOWNSHIP _____
OWNER Mayvin E Feldmeyer ADDRESS 6299 George Fox Dr, Galloway, Ohio 43119
LOCATION OF PROPERTY 6299 George Fox Drive

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST

(specify one by circling)

Casing diameter 5 1/2 inch Length of casing 90-0
Type of screen _____ Length of screen _____
Type of pump Submersible
Capacity of pump _____
Depth of pump setting 110-0
Date of completion Dec 22-1987

Test rate 20 gpm Duration of test 1 hrs
Drawdown 20-0 ft Date Dec 21-1987
Static level (depth to water) 70-0 ft
Quality (clear) (cloudy, taste, odor) _____
Pump installed by Dec 22-1987 Fred Kautz

WELL LOG*

SKETCH SHOWING LOCATION

Formations: sandstone, shale,
limestone, gravel, clay

From

To

Locate in reference to numbered
state highways, street intersections, county roads, etc.

Yellow Clay	0 ft	12- ft
Hardpan	12-	37-
Sand	37-	40-
Hardpan	40-	81-
Sand	81-	84-
Porous Rock	84-	90-
Limestone	90-	153

N
Interstate 70
Dreher Creek
George Fox Dr
Well 11
Alton
Route 70
W E
S

DRILLING FIRM

Fred Kautz

DATE

Dec 23 1987

ADDRESS

425 Alton Rd Galloway, Ohio

SIGNED

Fred Kautz

*If additional space is needed to complete well log, use next consecutive numbered form.

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224