

WELL LOG AND DRILLING REPORT

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

609267

41

COUNTY Tuscarawas TOWNSHIP Bucks SECTION OF TOWNSHIP 8
OWNER Delmer Youngen ADDRESS R#1 Baltic
LOCATION OF PROPERTY On C-Rd 46 3 mi. South of Baltic

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST

(specify one by circling)

Casing diameter 3 1/2 Length of casing 36'
Type of screen None Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion 7-17-84

Test rate 10 gpm Duration of test 1/2 hrs
Drawdown 0 ft Date _____
Static level (depth to water) 20' ft
Quality (clear) cloudy, taste, odor) _____
Pump installed by _____

WELL LOG*

SKETCH SHOWING LOCATION

Formations: sandstone, shale,
limestone, gravel, clay

From

To

Locate in reference to numbered
state highways, street intersections, county roads, etc.

Brown Shale

0 ft

22 ft

Gray Shale

22

60

W

N

E

S

DRILLING FIRM Charm Drilling Inc.
ADDRESS RR#4 Box 83 A Millersburg, O.

DATE 7-31-84

SIGNED Andrew N. Miller

*If additional space is needed to complete well log, use next consecutive numbered form.

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224

18