

WELL LOG AND DRILLING REPORT

NO CARBON PAPER
NECESSARY-
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

609850

COUNTY LUCAS TOWNSHIP Swanton SECTION OF TOWNSHIP _____

OWNER Lester E. Lewis ADDRESS 12210 Monclava Road

LOCATION OF PROPERTY_____

CONSTRUCTION DETAILS

Casing diameter 2 1/4" Length of casing 15

Type of screen 100 Grit Length of screen 3'

Type of pump Wax

Capacity of pump _____

Depth of pump setting _____

Date of completion July 17, 88

BAILING OR PUMPING TEST

(specify one by circling)

Test rate 6 gpm Duration of test 2 hrs

Drawdown _____ ft Date 7/18/88

Static level (depth to water) _____ ft

Quality (clear, cloudy, taste, odor) _____

Pump installed by self

WELL LOG*

**Formations: sandstone, shale,
limestone, gravel, clay**

From

To

0 ft | 18 ft

SKETCH SHOWING LOCATION

Locate in reference to numbered
state highways, street intersections, county roads, etc.

N

175

Leach Field ^{20'} 50

log

↓ ... ← 90° →

280

S

DRILLING FIRM Sc/P (HE DRILLED THIS WELL

DATE 8/4/88

ADDRESS 12210 MONCLOVA RD., SWANTON, OH 43558

SIGNED [Signature]

*If additional space is needed to complete well log, use next consecutive numbered form. LESTER E. LEWIS

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224