

WELL LOG AND DRILLING REPORT

NO CARBON PAPER
NECESSARY-
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

SOURCES
Permit # 45 611242

COUNTY Lucas TOWNSHIP Jerusalem SECTION OF TOWNSHIP 27
OWNER Les Ansel ADDRESS Oregon, O.
LOCATION OF PROPERTY 8246 Cedar Point Rd.

CONSTRUCTION DETAILS

Casing diameter 5 7/8 I.D. Length of casing 81'-6"
Type of screen _____ Length of screen _____
Type of pump Submersible
Capacity of pump 5 G.P.M.
Depth of pump setting 65
Date of completion 5-23-87

BAILING OR PUMPING TEST

(specify one by circling)

Test rate 12 gpm Duration of test 2 hrs
Drawdown 5 ft Date 5-25-87
Static level (depth to water) 30 ft
Quality (clear, cloudy, taste, odor) _____
Pump installed by Wendell Bihn

WELL LOG*[illegible]

SKETCH SHOWING LOCATION

Locate in reference to numbered
state highways, street intersections, county roads, etc.

A hand-drawn map showing a rectangular area. A horizontal line near the top is labeled "Cedar Point Rd". Just below this line, towards the right side, is an "X" marked "Well". The cardinal directions are indicated by large letters: "N" at the top, "S" at the bottom, "E" on the right, and "W" on the left. A vertical line runs from the "Cedar Point Rd" line down towards the bottom, dividing the rectangle into two parts.

DRILLING FIRM Burns Well Drilling
ADDRESS Walbridge O

DATE 5-25-87
SIGNED Wendell Bahr

*If additional space is needed to complete well log, use next consecutive numbered form.

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224