

WELL LOG AND DRILLING REPORT

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

611250

Permit # 72182

COUNTY Wood TOWNSHIP Center SECTION OF TOWNSHIP 13
OWNER Dorothy Davidson ADDRESS 7868 Housekeeper Rd.
Bowling Green, O
LOCATION OF PROPERTY 15861 Silver Wood Rd.

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST

(specify one by circling)

Casing diameter <u>5 5/8</u> Length of casing <u>33</u>	Test rate <u>10</u> gpm Duration of test <u>2</u> hrs
Type of screen _____ Length of screen _____	Drawdown <u>50</u> ft Date <u>June 30 1988</u>
Type of pump _____	Static level (depth to water) <u>12</u> ft
Capacity of pump _____	Quality (clear, cloudy, taste, odor) _____
Depth of pump setting _____	Pump installed by <u>Boos. Plumbing</u>
Date of completion _____	

WELL LOG*

SKETCH SHOWING LOCATION

Formations: sandstone, shale,
limestone, gravel, clay

From

To

Locate in reference to numbered
state highways, street intersections, county roads, etc.

Sand

0 ft

18 ft

Sand + Clay

18

30

Limer rock

30

95

N

Alexander

Well X

W

Housekeeper

E

Silverwood

DRILLING FIRM Bihn's Well Drilling

DATE June 30 88

ADDRESS Walbridge Ohio

SIGNED Wendell Bihn

*If additional space is needed to complete well log, use next consecutive numbered form.

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224