

WELL LOG AND DRILLING REPORT

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

30 OF
611282

COUNTY Ashtabula TOWNSHIP Rome SECTION OF TOWNSHIP Southern
OWNER Sandi Hought ADDRESS 3170 Rt 1 Dodgeville Rd Rome, O
LOCATION OF PROPERTY on Dodgeville Rd. 1/2 mi east of st. Rt 45

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST (specify one by circling)

Casing diameter 6" 00 Length of casing 25'
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion _____
Test rate 15 gpm Duration of test 3 hrs
Drawdown 27 ft Date 10-21-83
Static level (depth to water) 3 ft
Quality (clear, cloudy, taste, odor) Clear
Pump installed by _____

WELL LOG*

SKETCH SHOWING LOCATION

Formations: sandstone, shale,
limestone, gravel, clay

From

To

Locate in reference to numbered
state highways, street intersections, county roads, etc.

Clay

0 ft

4 ft

Gravel

4

8

Shale

8

45

Water 26'

W

N

Dodgeville Rd E

Dwell

ST RT 45

S

DRILLING FIRM Congdon Well Drilling DATE 10-24-83
ADDRESS 3280 Rt 465 Jefferson, Ohio 44047 SIGNED Don Congdon

*If additional space is needed to complete well log, use next consecutive numbered form.

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224

3170 Dodgeville Rd

(84)