

WELL LOG AND DRILLING REPORT

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

611294

COUNTY Ashtabula TOWNSHIP Colebrook SECTION OF TOWNSHIP Northeast
OWNER Richard Whiteley ADDRESS 915 E Windsor Rd. Colebrook O
LOCATION OF PROPERTY on Windsor Rd. 1/2 mile east of St. Rt 46 44034

CONSTRUCTION DETAILS

~~DRILLING~~ OR PUMPING TEST (specify one by circling)

Casing diameter <u>6 0.0.</u> Length of casing <u>37</u>	Test rate <u>30</u> gpm Duration of test <u>2</u> hrs
Type of screen _____ Length of screen _____	Drawdown <u>8</u> ft Date <u>6-30-84</u>
Type of pump _____	Static level (depth to water) <u>12</u> ft
Capacity of pump _____	Quality (clear, cloudy, taste, odor) <u>clear</u>
Depth of pump setting _____	Pump installed by _____
Date of completion _____	

WELL LOG*

SKETCH SHOWING LOCATION

Formations: sandstone, shale,
limestone, gravel, clay

From

To

Locate in reference to numbered
state highways, street intersections, county roads, etc.

Clay

0 ft

16 ft

Sand & Gravel

16

20

Shale

20

32

Sandstone

32

50

Water at 40'

W Windsor Rd

DWELL

DRILLING FIRM Congdon Well Drilling

DATE 6-30-84