

WELL LOG AND DRILLING REPORT

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

611983

COUNTY Stark TOWNSHIP Perry SECTION OF TOWNSHIP 23

John Lake, 3165 Rusty Ave. S.W., Canton, Ohio 44706

OWNER _____ ADDRESS _____

LOCATION OF PROPERTY same

CONSTRUCTION DETAILS

Casing diameter 5" Length of casing 71 3/4'
Type of screen _____ Length of screen _____
Type of pump Red Jacket submersible
Capacity of pump 10 gpm
Depth of pump setting approx. 220'
Date of completion 11-15-84

BAILING OR PUMPING TEST

(specify one by circling)

Test rate see below gpm Duration of test 2 hrs
Drawdown _____ ft Date 11-3-84
Static level (depth to water) _____ ft
Quality (clear, cloudy, taste, odor) clear; odorless;
17 grains hard; trace iron; 7.5 pH
Pump installed by Brogan Well Drilling Co.

WELL LOG*

Formations: <u>sandstone, shale,</u> <u>limestone, gravel, clay</u>	From	To
Clay	0 ft	30 ft
Sandstone	30'	48'
Shale	48'	70'
Shale	70'	90'
Limestone	90'	93'
Shale	93'	150'
Limestone	150'	152'
Shale	152'	210'
White sandstone	210'	230'
Shale	230'	253'

SKETCH SHOWING LOCATION

Locate in reference to numbered
state highways, street intersections, county roads, etc.

N

AIR TEST

253' - 40 gpm
210' - 40 gpm
190' - 20 gpm

W E

S

BROGAN WELL DRILLING COMPANY
DRILLING FIRM 7103 Columbus Rd. N.E.
ADDRESS Louisville, Ohio 44641

DATE November 15, 1984
SIGNED Paul D. Brogan

*If additional space is needed to complete well log, use next consecutive numbered form.

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224