

WELL LOG AND DRILLING REPORT

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

614267

COUNTY Union TOWNSHIP Allen SECTION OF TOWNSHIP Eastern
OWNER Rebecca Cardine ADDRESS 21100 S.R. 245 Marysville, Ohio
LOCATION OF PROPERTY 4 1/2 West of Marysville, Ohio, on S.R. 245

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST (specify one by circling)

Casing diameter 5" Length of casing 70
Type of screen - Length of screen -
Type of pump submersible
Capacity of pump 15 GPM
Depth of pump setting 30'
Date of completion -

Test rate 20 gpm Duration of test 6 hrs
Drawdown none ft Date Oct 5-83
Static level (depth to water) 15' ft
Quality (clear, cloudy, taste, odor) Clear
Pump installed by owner

WELL LOG*

SKETCH SHOWING LOCATION

Formations: sandstone, shale,
limestone, gravel, clay

From

To

Locate in reference to numbered
state highways, street intersections, county roads, etc.

<u>Clay</u>	0 ft	40 ft
<u>fine sand</u>	40	65
<u>gravel</u>	65	70

N

W 250' 0-well 4 1/2 miles E

SR 245

S

Marysville Ohio

DRILLING FIRM Moats Water Well Drilling
ADDRESS 745 N. Maple St. Marysville, Ohio 43040

DATE 10-5-83
SIGNED Richard A. Moats

*If additional space is needed to complete well log, use next consecutive numbered form.

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224