

WELL LOG AND DRILLING REPORT

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

614269

COUNTY Champaign TOWNSHIP Wayne SECTION OF TOWNSHIP East
OWNER Kenneth J. Bollock ADDRESS 7741 Mingo-Swirlburg Rd
LOCATION OF PROPERTY 3 Miles West of North Swirlburg, Ohio on Mingo Swirlburg Rd

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST
(specify one by circling)

(specify one by circling)

Casing diameter 5" Length of casing 52

Test rate 14 gpm Duration of test 100 hrs

Type of screen _____ Length of screen _____

Drawdown 1 ft Date 11-3-83

Type of pump Submersible

Static level (depth to water) 32 ft

Capacity of pump 15 H.P.H

Quality (clear, cloudy, taste, odor) Clear

Depth of pump setting 40'

Date of completion 11-10-83

Pump installed by Ormu

WELL LOG*

SKETCH SHOWING LOCATION

Formations: sandstone, shale,
limestone, gravel, clay

From

To

Locate in reference to numbered
state highways, street intersections, county roads, etc.

0 ft

15 ft

N

W

E

S

DRILLING FIRM

DATE 11-18-83