

WELL LOG AND DRILLING REPORT

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

616386

COUNTY Marion TOWNSHIP Pleasant SECTION OF TOWNSHIP _____
OWNER Donald Schrote ADDRESS 1252 Marion-Cardington Rd., East
LOCATION OF PROPERTY Same as above. (old house) (replacement well)

CONSTRUCTION DETAILS

Casing diameter 5" Length of casing 40
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting 45
Date of completion 10-8-87

BAILING OR PUMPING TEST

(specify one by circling)


Test rate 6 gpm Duration of test 24 hrs
Drawdown 0 ft Date 38'
Static level (depth to water) _____ ft
Quality (clear, cloudy, taste, odor) Clear, Sulphur odor
Pump installed by Chuck Ellsworth, Don Schrote

WELL LOG*

Formations: sandstone, shale, limestone, gravel, clay	From	To
Clay	0 ft	25 ft
Sand and Gravel	25	28
Clay	28	37
Limestone	37	60

SKETCH SHOWING LOCATION

Locate in reference to numbered
state highways, street intersections, county roads, etc.



DRILLING FIRM Ellsworth Well Drilling
ADDRESS 1240 Bellefontaine Ave. Marion

DATE October 10, 1987

SIGNED [Signature]

*If additional space is needed to complete well log, use next consecutive numbered form.

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224