

WELL LOG AND DRILLING REPORT

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

617719

COUNTY Fairfield TOWNSHIP Bloom SECTION OF TOWNSHIP Winchester Rd
OWNER Allen Stout ADDRESS 7610 Winchester Rd
LOCATION OF PROPERTY 200 ft west Pickerington & Winchester Rd

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST

(specify one by circling)

Casing diameter 5 1/2" Length of casing _____
Type of screen perforated Length of screen 2 1/2'
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion 7-10-87

Test rate 10 gpm Duration of test 1 hrs
Drawdown 5 ft Date 7-9-87
Static level (depth to water) _____ ft
Quality (clear, cloudy, taste, odor) cloudy
Pump installed by Owner

WELL LOG*

SKETCH SHOWING LOCATION

Formations: sandstone, shale,
limestone, gravel, clay

From

To

Locate in reference to numbered
state highways, street intersections, county roads, etc.

Soil & clay
grey clay
sand + gravel
water at 60-61

0 ft

15 ft

15

58

58

62

W

N

E

S

DRILLING FIRM

Mulheisen Well Drilling

DATE

9-9-87

ADDRESS

Box 27 Amanda Ohio

SIGNED

Larry K. Mulheisen

*If additional space is needed to complete well log, use next consecutive numbered form.

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224