WELL LOG AND DRILLING REPORT

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

NO CARBON PAPER NECESSARY– SELF-TRANSCRIBING

301

617720

COUNTY Fairfield TOWNSHIP Violet SECTION OF TOWNSHIP

OWNER Wesley E Thorne ADDRESS 7501 Columbus-Lancaster Rd

LOCATION OF PROPERTY 1st road south of pickerington Rd on 33 south - across railroad tracks -

CONSTRUCTION DETAILS

Casing diameter 5 1/2 Length of casing 62 ft

Type of screen perforated Length of screen 2 1/2 ft

Type of pump Red Jacket

Capacity of pump 10 gpm

Depth of pump setting 52 ft

Date of completion 10-6-86

BAILING OR PUMPING TEST
(specify one by circling)

Test rate 15 gpm Duration of test 1 hrs

Drawdown 10 ft Date 10-5-86

Static level (depth to water) 32 ft ft

Quality (clear, cloudy, taste, odor) Cloudy

Pump installed by Mullins Well Drilling

WELL LOG*

Formations: sandstone, shale, limestone, gravel, clay	From	To
soil & clay	0 ft	15 ft
~~clay~~ clay & gravel	15	54
sand & gravel	54	62
water at 61 ft		

SKETCH SHOWING LOCATION

Locate in reference to numbered state highways, street intersections, county roads, etc.



DRILLING FIRM Mullins Well Drilling DATE 10-20-87

ADDRESS Box 277 Amanda, Ohio SIGNED Larry K Mullins

*If additional space is needed to complete well log, use next consecutive numbered form.

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224

375