

WELL LOG AND DRILLING REPORT

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

618148

(Koz)

COUNTY FAIRFIELD TOWNSHIP VIOLET SECTION OF TOWNSHIP _____

OWNER MARTIN PASSAGUA ADDRESS DATY RD.

LOCATION OF PROPERTY 1/4 M. N. OF #256 ON DUTY RD. 9757

CONSTRUCTION DETAILS

Casing diameter 4 1/4 Length of casing 75

Type of screen _____ Length of screen _____

Type of pump

Capacity of pump

Depth of pump setting

Date of completion

BAILING OR PUMPING TEST
(specify one by circling)

(specify one by circling)

Test rate 16 gpm Duration of test 2 hrs

Drawdown 8 ft

Date _____

Static level (depth to water) 10 ft. ft

Quality (clear, cloudy, taste, odor)._____

Pump installed by _____

WELL LOG*

Formations: sandstone, shale,
limestone, gravel, clay

From

To

CLAY	0 ft	28 ft
------	------	-------

DIRTY SAND + GRAVEL	28	34
---------------------	----	----


CLAY	34	70
------	----	----

SOFT ROCK	70	75
-----------	----	----

HARD ROCK	75	82
-----------	----	----

SKETCH SHOWING LOCATION

Locate in reference to numbered
state highways, street intersections, county roads, etc.



DRILLING FIRM SAM Lewis

ADDRESS 1913 Todd Ave.

DATE JAN. 15, 1988

SIGNED Sam Lewis

*If additional space is needed to complete well log, use next consecutive numbered form.

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224 203