

WELL LOG AND DRILLING REPORT

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

620102

COUNTY Allen TOWNSHIP Jackson SECTION OF TOWNSHIP 1
OWNER Roger Plautner ADDRESS 11318 Huber Rd Bluffton, OH
LOCATION OF PROPERTY 11318 Huber Rd 1/2 mi West of Harkins Run

CONSTRUCTION DETAILS

Casing diameter 4 1/4 Length of casing 32'
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion 5-20-83

BAILING OR PUMPING TEST Co Line (specify one by circling)

Test rate 30 gpm Duration of test 2 hrs
Drawdown 0 ft Date 5-20-83
Static level (depth to water) 12' ft
Quality (clear, cloudy, taste, odor) clear
Pump installed by _____

WELL LOG*

Formations: sandstone, shale,
limestone, gravel, clay


From

To

yellow clay	0 ft	15' ft
Blue clay	15	29
Limestone	29	50

SKETCH SHOWING LOCATION

Locate in reference to numbered
state highways, street intersections, county roads, etc.



DRILLING FIRM Willard Shulow DATE 5-20-83
ADDRESS 1822 SR 81 Adas SIGNED Willard Shulow

*If additional space is needed to complete well log, use next consecutive numbered form.

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224