WELL LOG AND DRILLING REPORT

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

NO CARBON PAPER NECESSARY – SELF-TRANSCRIBING

622901

COUNTY Geauga TOWNSHIP Hambden SECTION OF TOWNSHIP

OWNER Anna Stagel ADDRESS 14940 Rt 6 Hambden Twp

LOCATION OF PROPERTY

CONSTRUCTION DETAILS

Casing diameter 6" Length of casing 42'

Type of screen Length of screen

Type of pump

Capacity of pump

Depth of pump setting

Date of completion

BAILING OR PUMPING TEST
(specify one by circling)

Test rate 10 gpm Duration of test 2 hrs

Drawdown Complete ft Date 9-15-83

Static level (depth to water) 8' ft

Quality (clear, cloudy, taste, odor) clear

Pump installed by

WELL LOG*

Formations: sandstone, shale, limestone, gravel, clay	From	To
Clay - Brown	0 ft	5 ft
Clay - Gray	5	18
Sand Gravel & Clay	18	30
Sand Gravel & C	30	39
Hard Shale	39	88
3 GPM at 43'		
7 GPM between	65' and	88'

SKETCH SHOWING LOCATION

Locate in reference to numbered state highways, street intersections, county roads, etc.



DRILLING FIRM C.A.P. Drilling DATE 9-15-83

ADDRESS 7647 Dewey Rd Thompson, O SIGNED Martin Gaut

*If additional space is needed to complete well log, use next consecutive numbered form.

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224