WELL LOG AND DRILLING REPORT

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

NO CARBON PAPER NECESSARY— SELF-TRANSCRIBING

622902

COUNTY Geauga TOWNSHIP Hambden SECTION OF TOWNSHIP

OWNER Gene Braun ADDRESS 9436 Wildwood Dr. S/L 14

LOCATION OF PROPERTY

CONSTRUCTION DETAILS		BAILING OR PUMPING TEST (specify one by circling)	
Casing diameter 6"	Length of casing 72'	Test rate 15 gpm (12GPm)	Duration of test 18 hrs
Type of screen	Length of screen	Drawdown 20' ft	Date 9-20-83
Type of pump		Static level (depth to water) 36' ft	
Capacity of pump		Quality (clear, cloudy, taste, odor) Clear	
Depth of pump setting			
Date of completion		Pump installed by	

WELL LOG*

Formations: sandstone, shale, limestone, gravel, clay	From	To
Clay	0 ft	6 ft
Clay-Sand + Gravel	6	50
Sand Gravel	50	69
Hard Shale	69	84
Water from 72' to 84'		

SKETCH SHOWING LOCATION

Locate in reference to numbered state highways, street intersections, county roads, etc.



DRILLING FIRM C.A.P. Drilling Co. DATE 9-20-83

ADDRESS 7647 Dewey Rd Thompson SIGNED [signature]

*If additional space is needed to complete well log, use next consecutive numbered form.

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224