

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

COUNTY Fulton TOWNSHIP Chesterfield SECTION OF TOWNSHIP 27
OWNER James Barhite ADDRESS 13447 St. Route 108, Wauseon, Ohio
LOCATION OF PROPERTY 1/2 mile south of Oakshade on west side of State Route 108 - 250' West of Rt. 108

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST
(specify one by circling)

(specify one by circling)

Casing diameter 7" Length of casing 65'
Type of screen Stainless Steel Length of screen 5'6"
Type of pump Not installed
Capacity of pump Pump not installed
Depth of pump setting _____
Date of completion Well completed drilling 12-15-83

Test rate 12 gpm Duration of test 1 hr.30min hrs
Pumping level xxx 45'
Drawdown _____ ft Date 12-15-83
Static level (depth to water) 11 feet ft
Quality (clear, cloudy, taste, odor) _____

Pump installed by Not installed

WELL LOG*

SKETCH SHOWING LOCATION

Formations: sandstone, shale,
limestone, gravel, clay

From

To

Locate in reference to numbered
state highways, street intersections, county roads, etc.

Dirty Sand

0 ft

11 ft

Blue Clay

11'

59'

Fine blue sand

59'

70'

W

9

DRILLING FIRM Dunbar Drilling Inc.

DATE 12-23-83

ADDRESS 307 Broadway, Swanton, Ohio 43558

SIGNED

Mary R. Stark, Treasurer

*If additional space is needed to complete well log, use next consecutive numbered form.

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224

30