

WELL LOG AND DRILLING REPORT

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

623455

COUNTY MAHONING TOWNSHIP Goshen SECTION OF TOWNSHIP 23
OWNER Pauline Steves ADDRESS 12920 Goshen Rd. Salem, Oh.
LOCATION OF PROPERTY 12920 Goshen Rd Salem, Ohio 44460

CONSTRUCTION DETAILS

Casing diameter 6" Length of casing 37'

Type of screen _____ Length of screen _____

Type of pump Deming Submersible

Capacity of pump 7 GPM

Depth of pump setting 55'

Date of completion Oct. 9, 1984

BAILING OR PUMPING TEST
(specify one by circling)

Test rate 20 gpm Duration of test 4 hrs

Drawdown 20' to 60 ft. Date Sept. 29

Static level (depth to water) 40' ft

Quality (clear, cloudy, taste, odor) Good

Pump installed by Lisbon Well Drilling

WELL LOG*[illegible]

SKETCH SHOWING LOCATION

Locate in reference to numbered
state highways, street intersections, county roads, etc.

Rt 165

SEC. 23

KENT RD.

Goshen Rd.

N

W

S

45 BYPASS

DRILLING FIRM Lisbon Well Drilling

ADDRESS 7524 1/2 S.R. 45 Lisbon, Oh.

DATE Oct. 11, 1984

SIGNED Ber Reynolds

*If additional space is needed to complete well log, use next consecutive numbered form.

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224