

WELL LOG AND DRILLING REPORT

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

623543

COUNTY Greene TOWNSHIP Spring Valley SECTION OF TOWNSHIP _____
OWNER Dale Henkener ADDRESS 9001 Washington Mill Rd.
LOCATION OF PROPERTY ~~1 mile west of Lower Bellbrook Rd.~~ 1 mile west of Lower Bellbrook Rd., O

CONSTRUCTION DETAILS

Casing diameter 6 Length of casing 295
Type of screen _____ Length of screen _____
Type of pump _____
Capacity of pump _____
Depth of pump setting _____
Date of completion 3/25/85

BAILING OR PUMPING TEST (specify one by circling)


Test rate 20 gpm Duration of test 2 hrs
Drawdown 10 ft Date 3/25/85
Static level (depth to water) 120 ft
Quality (clear, cloudy, taste, odor) clear
Pump installed by _____

WELL LOG*

Formations: sandstone, shale, limestone, gravel, clay	From	To
Clay	0 ft	60 ft
sand + gravel	60	66
Clay	66	160
gravel	160	165
Clay	165	293
gravel	293	295
water	295	

SKETCH SHOWING LOCATION

Locate in reference to numbered
state highways, street intersections, county roads, etc.



DRILLING FIRM

Eddie Behor

DATE

4/12/85