

WELL LOG AND DRILLING REPORT

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

624562

COUNTY WOOD TOWNSHIP HEATLY SECTION OF TOWNSHIP _____
OWNER ANN + GREG CLAMM ADDRESS 312 N. SECOND ST.
LOCATION OF PROPERTY 1145 N. BALTIMORE RD.

CONSTRUCTION DETAILS

Casing diameter 6" Length of casing 29'
Type of screen — Length of screen —
Type of pump NA
Capacity of pump _____
Depth of pump setting _____
Date of completion _____

BAILING OR PUMPING TEST (Specify one by circling)

Test rate 8 gpm Duration of test 1 hrs
Drawdown 16 ft Date 8/31/86
Static level (depth to water) 17 ft
Quality (clear, cloudy, taste, odor) CLEAR
Pump installed by NA

WELL LOG*

Formations: sandstone, shale,
limestone, gravel, clay


From

To

RED CLAY	0 ft	15 ft
GREY CLAY	15	27
ROCK	27	57
WATER	57	

SKETCH SHOWING LOCATION

Locate in reference to numbered
state highways, street intersections, county roads, etc.



DRILLING FIRM KING WELL DRILLING
ADDRESS BOX 988 VAN BUREN, OH

DATE 8/31/86
SIGNED Michael L. L...

*If additional space is needed to complete well log, use next consecutive numbered form.

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224