

WELL LOG AND DRILLING REPORT

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

629947

COUNTY Carroll TOWNSHIP Harmon SECTION OF TOWNSHIP _____
OWNER Daniel B Wells ADDRESS 5060 Meadow Rd.
LOCATION OF PROPERTY 5060 MEADOW RD, KENSINGTON OHIO

CONSTRUCTION DETAILS	BAILING OR PUMPING TEST (specify one by circling)
Casing diameter <u>5"</u> Length of casing <u>29 FT</u>	Test rate <u>10</u> gpm Duration of test <u>20 MIN</u> hrs
Type of screen _____ Length of screen _____	Drawdown <u>NONE</u> ft Date <u>11-15-94</u>
Type of pump <u>1/2 H.P. SUB.</u>	Static level (depth to water) <u>10</u> ft
Capacity of pump <u>10 GAL PER MIN</u>	Quality (clear, cloudy, taste, odor) _____
Depth of pump setting <u>47 FT</u>	
Date of completion <u>11-15-94</u>	Pump installed by <u>WILLIAM HAMPSON</u>

WELL LOG*			SKETCH SHOWING LOCATION
Formations: sandstone, shale, limestone, gravel, clay	From	To	Locate in reference to numbered state highways, street intersections, county roads, etc.
<u>SHALE</u>	0 ft	<u>20</u> ft	N E S W <u>KENSINGTON</u> <u>RT 9</u> <u>WELL TRAIL</u> <u>100 FT</u> <u>SEPTIC</u> <u>MEADOW RD</u> <u>TODD HAWK</u>
<u>CLAY</u>	20	25	
<u>SHALE & SAND</u>	25	52	

DRILLING FIRM HAMPSON DRILLING
ADDRESS 155 S STATE BLVD

DATE William Hampson
SIGNED 11-15-94