

WELL LOG AND DRILLING REPORT

NO CARBON PAPER
NECESSARY-
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

630931

COUNTY Manassas TOWNSHIP [REDACTED] SECTION OF TOWNSHIP North
OWNER Alan Walham ADDRESS 4621 Woodhurst St
Springtown Ohio
LOCATION OF PROPERTY 10251 Calhoun Rd 5-7, 23

CONSTRUCTION DETAILS

Casing diameter 4 7/8 Length of casing 1 1/2
Type of screen ✓ Length of screen —
Type of pump —
Capacity of pump —
Depth of pump setting 180
Date of completion 3 10 - 89

BAILING OR PUMPING TEST

(specify one by circling)

Test rate 8 gpm Duration of test 1 hrs
Drawdown 160 ft Date 3 11 89
Static level (depth to water) 48 ft
Quality (clear, cloudy, taste, odor) _____
Pump installed by Drumler

WELL LOG*

Formations: sandstone, shale,
limestone, gravel, clay

From

To

clay yellow	0 ft	12 ft
clay gray	12	42
sand & clay	42	135
gravel & sand	135	180
shale	180	194
stone	194	199

SKETCH SHOWING LOCATION

Locate in reference to numbered
state highways, street intersections, county roads, etc.

N

pt
45

Calla R4

W

E

S

DRILLING FIRM J. L. Co.
ADDRESS 9645 Martin Rd N. Benton

DATE 2-11-71

SIGNED [Signature]

*If additional space is needed to complete well log, use next consecutive numbered form.

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224

(52)