WELL LOG AND DRILLING REPORT

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

CARBON PAPER NECESSARY – SELF-TRANSCRIBING

631208

COUNTY Mahoning TOWNSHIP Canfield SECTION OF TOWNSHIP

OWNER Richard Seamon ADDRESS 6130 Gibson Rd.

LOCATION OF PROPERTY 6130 Gibson Rd.

CONSTRUCTION DETAILS

Casing diameter 6 Length of casing 38

Type of screen Length of screen

Type of pump Sub

Capacity of pump 10

Depth of pump setting 80 ft.

Date of completion 5-10-87

BAILING OR PUMPING TEST
(specify one by circling)

Test rate 10 gpm Duration of test 1 hrs

Drawdown 80 ft ft Date 5-10-87

Static level (depth to water) ft

Quality (clear, cloudy, taste, odor)

Pump installed by Driller

WELL LOG*

Formations: sandstone, shale, limestone, gravel, clay	From	To
Clay	0 ft	18 ft
Shale	18	105
Sandy Shale	105	143
Sandstone	143	150

SKETCH SHOWING LOCATION

Locate in reference to numbered state highways, street intersections, county roads, etc.



DRILLING FIRM Reuds Lawn DATE 5-10-87

ADDRESS 3593 Butler-Grange SIGNED Wm Reudslawn

*If additional space is needed to complete well log, use next consecutive numbered form.

14

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224