

WELL LOG AND DRILLING REPORT

State of Ohio

DEPARTMENT OF NATURAL RESOURCES

Division of Water

Fountain Square

Columbus, Ohio 43224

NO CARBON PAPER

NECESSARY -

SELF-TRANSCRIBING

632589

COUNTY 10 TOWNSHIP Van SECTION OF TOWNSHIP

OWNER D. L. Borders ADDRESS 1000 1st St. S.E.

LOCATION OF PROPERTY 51 Kennedy Avenue

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST

(specify one by circling)

Casing diameter 7.5 Length of casing 6 Test rate 10 gpm Duration of test 2 hrs

Type of screen _____ Length of screen _____ Drawdown 164 ft Date 2/2/54

Type of pump _____ Static level (depth to water) _____ ft

Capacity of pump _____ Quality (clear, cloudy, taste, odor) _____

Depth of pump setting _____

Date of completion _____ Pump installed by _____

WELL LOG*

SKETCH SHOWING LOCATION

Formations: sandstone, shale,
limestone, gravel, clay

From

To

Locate in reference to numbered
state highways, street intersections, county roads, etc.

N

W

F

S

DRILLING FIRM W. M. W. Co.

DATE 12/10/00

ADDRESS 10901 C-72

SIGNED _____

• If additional space is needed to complete well log, use next consecutive numbered form.

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224

⑧