WELL LOG AND DRILLING REPORT

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

NO CARBON PAPER NECESSARY– SELF-TRANSCRIBING

633197

COUNTY Pike TOWNSHIP Seal SECTION OF TOWNSHIP

OWNER Ellis Hill ADDRESS 120 Cornett Hill Rd.

LOCATION OF PROPERTY 120 Cornett Hill Rd. Piketon Oh

CONSTRUCTION DETAILS

Casing diameter 6" Length of casing 30'

Type of screen Length of screen

Type of pump

Capacity of pump

Depth of pump setting

Date of completion 6-11-93

BAILING OR PUMPING TEST
(specify one by circling)

Test rate 4 gpm Duration of test 20 hrs

Drawdown Dry ft Date

Static level (depth to water) ft

Quality (clear, cloudy, taste, odor) Clear

Pump installed by

WELL LOG*

Formations: sandstone, shale, limestone, gravel, clay	From	To
Top soil	0 ft	5 ft
Gam Clay	5	22
sand	22	28
Gray shale	28	64
Black shale	64	78

SKETCH SHOWING LOCATION

Locate in reference to numbered state highways, street intersections, county roads, etc.



DRILLING FIRM Mathews Well Drilling DATE 6-23-93

ADDRESS 2289 Dutch Hollow Rd. Beaver, Oh. SIGNED [signature]

*If additional space is needed to complete well log, use next consecutive numbered form.

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224