

WELL LOG AND DRILLING REPORT

NO CARBON PAPER
NECESSARY-
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

635114

COUNTY LUCAS TOWNSHIP SYLVANIA SECTION OF TOWNSHIP _____
OWNER JIM MORIARTY ADDRESS 9056 SYL-MET. RD, SYLVANIA, OHIO
LOCATION OF PROPERTY ON CORNER OF SYL-MET. RD AND MITCHAM ON NO. E. SIDE 43560

CONSTRUCTION DETAILS

Casing diameter 5" Length of casing 38'
Type of screen Length of screen
Type of pump
Capacity of pump
Depth of pump setting
Date of completion 6-3-86

BAILING OR PUMPING TEST

(specify one by circling)

Test rate _____ gpm Duration of test _____ hrs
 Drawdown _____ ft Date _____
 Static level (depth to water) _____ 9 _____ ft
 Quality (clear, cloudy, taste, odor) _____

 Pump installed by _____

WELL LOG*[illegible]

SKETCH SHOWING LOCATION

Locate in reference to numbered
state highways, street intersections, county roads, etc.

A hand-drawn map showing the intersection of two roads. A vertical line represents S. Pitcher Rd, with 'S' at the bottom and 'N' at the top. A horizontal line represents W. Syl-Met Rd, with 'W' on the left and 'E' on the right. The intersection is marked with a small square containing an 'X'. The road names are written vertically along their respective lines.

DRILLING FIRM GERARD BETTINGER DATE 6-11-86
ADDRESS 5021 NO. BERKEY ST. R. BERKEY, SIGNED Gerard Bettinger
*If additional space is needed to complete well log, use next consecutive numbered form.

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224