

WELL LOG AND DRILLING REPORT

NO CARBON PAPER
NECESSARY-
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

635117

COUNTY LUCAS TOWNSHIP RICHFIELD SECTION OF TOWNSHIP _____
OWNER MICHAEL DAVENPORT ADDRESS 6018 GLASGOW, SYLVANIA, OHIO
LOCATION OF PROPERTY ON KILBURN RD. No. OF BRINT RD. WEST SIDE

CONSTRUCTION DETAILS.

Casing diameter 5" Length of casing 43'

Type of screen _____ Length of screen _____

Type of pump _____

Capacity of pump _____

Depth of pump setting _____

Date of completion SEPT. 26, 1986

BAILING OR PUMPING TEST

(specify one by circling)

Test rate gpm Duration of test hrs

Drawdown _____ ft Date _____

Static level (depth to water) 16 ft

Quality (clear, cloudy, taste, odor) _____

Pump installed by _____

WELL LOG*

Formations: sandstone, shale,
limestone, gravel, clay

From

To

0 ft	13 ft
------	-------

13.	40.
-----	-----

40	43
----	----

43	70
----	----

WATER AT 43'

SKETCH SHOWING LOCATION

Locate in reference to numbered
state highways, street intersections, county roads, etc.

N

W BRINT Rd

F

KILBURN RD

S

DRILLING FIRM GERARD BETTINGER

DATE 1 OCT 4 1986

ADDRESS 5021 W. BERKEY SQ. BERKEY, OHIO
43501

SIGNED L. H. Hays 12.14.1968
 secutive-numbered form.

• If additional space is needed to complete well log, use next consecutive numbered form.

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224