

WELL LOG AND DRILLING REPORT

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

636835

COUNTY SENECA TOWNSHIP PLEASANT SECTION OF TOWNSHIP _____
OWNER DALE STACY ADDRESS 9000 N CO RD 51 GREENSPRING
LOCATION OF PROPERTY SW Side of Tipple Rd where Sandusky Co 113 DEAD ENDS

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST

(specify one by circling)

Casing diameter 7' Length of casing 73' Test rate 60 gpm Duration of test 2 hrs
Type of screen _____ Length of screen _____ Drawdown 75 ft Date 5-8-89
Type of pump _____ Static level (depth to water) 21' ft
Capacity of pump _____ Quality (clear, cloudy, taste, odor) CLEARED UP
Depth of pump setting _____ 1 hr 2 hrs
Date of completion 5-10-89 Pump installed by _____

WELL LOG*

SKETCH SHOWING LOCATION

Formations: sandstone, shale,
limestone, gravel, clay

From

To

Locate in reference to numbered
state highways, street intersections, county roads, etc.

SAND & GRAVEL

30 ft

15 ft

SOFT SHALE

15

70

BROKEN LIME

70

74

SAND & GRAVEL

BROWN LIME

74

125'

WATER

10.5'

EST 60 gal per min at 75' depth
Blow 2 hrs.

W

23' of 10" Conductor Cemented
73' of 7" Cemented to Surface

N

SANDUSKY CO.

SANDUSKY CO 113

SENECA CO

E

S

DRILLING FIRM SPENCER DRILLING

DATE 5-10-89

ADDRESS VAN LUE OHIO #255

SIGNED Lee S. Spencer

*If additional space is needed to complete well log, use next consecutive numbered form.

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224