

WELL LOG AND DRILLING REPORT

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

638540

Jefferson

COUNTY RICHLAND TOWNSHIP BERLIN SECTION OF TOWNSHIP _____

OWNER BRAD WALKER ADDRESS 7448 St. Rt. 13 S. Bellville, Oh. 44813

LOCATION OF PROPERTY same

CONSTRUCTION DETAILS

Casing diameter 4 1/2" ID Length of casing 94 ft.

Type of screen _____ Length of screen _____

Type of pump 1/2 hp. Myers submersible

Capacity of pump 11 gpm at 50'

Depth of pump setting 100 ft.

Date of completion 1-23-88

BAILING OR PUMPING TEST

(specify one by circling)

Test rate 20 gpm Duration of test 2 hrs

Drawdown 0 ft Date January 23, 1988

Static level (depth to water) 37 ft. ft

Quality (clear, cloudy, taste, odor) clear


Pump installed by A-1 PUMP AND DRILLING CO.

WELL LOG*

Formations: sandstone, shale, limestone, gravel, clay	From	To
CLAY	0 ft	73 ft
CLAY & FINE GRAVEL	73'	84'
SANDSTONE	84'	103'
SHALE	103'	110'

SKETCH SHOWING LOCATION

Locate in reference to numbered
state highways, street intersections, county roads, etc.



DRILLING FIRM A-1 PUMP AND DRILLING CO.

ADDRESS 232 Markey St. Bellville, Oh.

DATE January 23, 1988

SIGNED James C. Findley

*If additional space is needed to complete well log, use next consecutive numbered form.