

RT 167 *Res*
638831

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

638831

La Co # 9751

COUNTY GEORGIA TOWNSHIP Chardon SECTION OF TOWNSHIP 2
OWNER John S Wilbur ADDRESS 9935 Mitchell Mill Rd ^{number 40200}
LOCATION OF PROPERTY 9935 Mitchell Mill Rd

CONSTRUCTION DETAILS			BAILING OR PUMPING TEST (specify one by circling)	
Casing diameter <u>6"</u>	Length of casing <u>325'</u>		Test rate <u>30+</u> gpm	Duration of test <u>1</u> hrs
Type of screen <u>NONE</u>	Length of screen _____		Drawdown <u>49</u> ft	Date _____
Type of pump <u>NONE</u>			Static level (depth to water) <u>26'</u> ft	
Capacity of pump _____			Quality (clear, cloudy, taste, odor) _____	
Depth of pump setting _____			<u>clear</u>	
Date of completion _____			Pump installed by <u>NONE</u>	
WELL LOG*			SKETCH SHOWING LOCATION	
Formations: sandstone, shale, limestone, gravel, clay	From	To	Locate in reference to numbered state highways, street intersections, county roads, etc.	
<u>yellow clay</u>	0 ft	9 ft	N W E S	
<u>shale</u>	9	75'		
<u>Test Well</u>				

DRILLING FIRM Anderson Inc.

DATE 9/15/87

ADDRESS Bf 1644 6th

SIGNED 2/15/76 - V

*If additional space is needed to complete well log, use next consecutive numbered form.

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224

289