

WELL LOG AND DRILLING REPORT

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

652692

COUNTY Portage TOWNSHIP Brimfield SECTION OF TOWNSHIP North
OWNER Tim Steiner ADDRESS 5160 Troyer Rd.
LOCATION OF PROPERTY corner of Troyer & Hall Dr.

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST (specify one by circling)

Casing diameter <u>5"</u> Length of casing <u>128</u>	Test rate <u>15</u> gpm Duration of test <u>1</u> hrs
Type of screen <u>None</u> Length of screen _____	Drawdown <u>40</u> ft Date <u>11-3-86</u>
Type of pump _____	Static level (depth to water) <u>45</u> ft
Capacity of pump _____	Quality <u>(clear)</u> (clear, cloudy, taste, odor) _____
Depth of pump setting _____	Pump installed by <u>plumber</u>
Date of completion _____	

WELL LOG*

SKETCH SHOWING LOCATION

Formations: sandstone, shale,
limestone, gravel, clay

From

To

Locate in reference to numbered
state highways, street intersections, county roads, etc.

Brown Clay

0 ft

21 ft

Gray Clay

21

122

Sand

122

128

Sandstone

128


130

N

W

E

S



DRILLING FIRM Streetsboro Sales & Service DATE 11-3-86
ADDRESS 9158 S.R. 14 Streetsboro Ohio SIGNED Larry Dean

*If additional space is needed to complete well log, use next consecutive numbered form.

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224

(28)