

WELL LOG AND DRILLING REPORT

NO CARBON PAPER
NECESSARY—
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

652698

COUNTY Stark TOWNSHIP Nimishillen SECTION OF TOWNSHIP South west
OWNER Lee Dalton ADDRESS 3115 Long Ave. Canton
LOCATION OF PROPERTY 1 mile East of Fairhope

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST

(Specify one by circling)

Casing diameter <u>5 1/2"</u> Length of casing <u>48 ft</u>	Test rate <u>5 1/2</u> gpm Duration of test <u>.5</u> hrs
Type of screen <u>None</u> Length of screen _____	Drawdown <u>20</u> ft Date <u>Nov 86</u>
Type of pump _____	Static level (depth to water) <u>55</u> ft
Capacity of pump _____	Quality <u>(clear)</u> cloudy, taste, odor) _____
Depth of pump setting _____	Pump installed by <u>plumber</u>
Date of completion _____	

WELL LOG*

SKETCH SHOWING LOCATION


Formations: sandstone, shale,
limestone, gravel, clay

From

To

Locate in reference to numbered
state highways, street intersections, county roads, etc.

Clay	0 ft	12 ft
Sandstone	12	19
Soft shale	19	48
Shale	48	46



351 AA Well & Pump, Co.
DRILLING FIRM Streetsboro Sales & Service

DATE 12-2-86

ADDRESS 4956 S.R. 14 Streetsboro Ohio

SIGNED Jerry Dean

*If additional space is needed to complete well log, use next consecutive numbered form.

ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224