

671016

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

Permit Number 371 452

COUNTY MARION TOWNSHIP Richland SECTION OF TOWNSHIP _____
OWNER LARRY Wite ADDRESS 3366 Cl. Land. Rd 5. / SR. 98
LOCATION OF PROPERTY _____

BAILING OR PUMPING TEST
(specify one by circling)

Test rate 15 gpm Duration of test 2 hrs
Drawdown 8 ft Date 8-25-91
Static level (depth to water) 43' ft
Quality (clear, cloudy, taste, odor)
White Sulphur
Pump installed by Hines Drilling

SKETCH SHOWING LOCATION

Locate in reference to numbered state highways, street intersections, county roads, etc.

A hand-drawn map showing the location of Larry Wite. The map features a vertical line labeled "S R 96" at the bottom and a horizontal line labeled "MARION Co Rd 163". A north arrow is at the top, and a west arrow is on the left. A small square with a dot inside is labeled "LARRY WITE". The text "MARION Co Rd 142" is written above the horizontal line.

DNR 7802

ADDRESS Ashtabula Ohio SIGNED Edward F. Hines

Completion of this form is required by 1521.05, Ohio Revised Code - file within 30 days after completion.

WHITE ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224 / Blue - Customer's Copy / Pink - Driller's Copy / Green - Local Health Dept. Copy

