

671018

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

Permit Number 989-92

COUNTY MORROW TOWNSHIP CARLINGTON SECTION OF TOWNSHIP _____
OWNER MELVIN ROUSE ADDRESS 3706 U.S. Route 42
LOCATION OF PROPERTY 1 Mile South of CARLINGTON ON U.S. 42

CONSTRUCTION DETAILS		BAILING OR PUMPING TEST (specify one by circling)	
Casing diameter <u>5"</u>	Length of casing <u>29</u>	Test rate <u>15</u> gpm	Duration of test <u>3</u> hrs
Type of screen <u>Perf</u>	Length of screen <u>3'</u>	Drawdown <u>8</u> ft	Date <u>6-12-92</u>
Type of pump <u>Sub</u>		Static level (depth to water) <u>11'</u>	ft
Capacity of pump <u>10 G.P.M.</u>		Quality (clear, cloudy, taste, odor) <u>CLEAR</u>	
Depth of pump setting <u>28'</u>			
Date of completion <u>6-12-92</u>		Pump installed by <u>OTHER</u>	
Rotary ☐ or Cable ☒			

[illegible]

DNR 7802

DRILLING FIRM Homer Drilling REGISTRATION NUMBER 14-24 DATE 6-12-92
ADDRESS 43 W. High Ashley Ohio SIGNED Ed. Homer

Completion of this form is required by 1521.05, Ohio Revised Code - file within 30 days after completion.

WHITE ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224 / Blue - Customer's Copy / Pink - Driller's Copy / Green - Local Health Dept. Copy