

WELL LOG AND DRILLING REPORT

671352

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

Permit Number _____

COUNTY MIAMI TOWNSHIP Bethel SECTION OF TOWNSHIP _____
OWNER Bancroft & Vermillion ADDRESS 5819 Weynagite Rd
LOCATION OF PROPERTY Same

CONSTRUCTION DETAILS

Casing diameter 5 5/8 Length of casing 27
Type of screen _____ Length of screen _____
Type of pump Submersible
Capacity of pump 10
Depth of pump setting 92
Date of completion 5 April 1988
Rotary ☐ or Cable ☒

BAILING OR PUMPING TEST

(specify one by circling)


Test rate 10 gpm Duration of test 1 hrs
Drawdown 10 ft Date 3 April 88
Static level (depth to water) 50 ft
Quality (clear, cloudy, taste, odor) Clear
Pump installed by SC Patterson

WELL LOG*

Formations: sandstone, shale, limestone, gravel, clay	From	To
<u>Clay</u>	<u>0</u> ft	<u>7</u> ft
<u>Limestone</u>	<u>7</u>	<u>120</u>
<u>Reamed & Cemented</u>		
<u>Casing</u>		
<u>Water</u>	<u>110</u>	<u>120</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
state highways, street intersections, county roads, etc.



* If additional space is needed to complete well log, use next consecutively numbered form.

DNR 7802

DRILLING FIRM Patterson Well Co REGISTRATION NUMBER 184 DATE 9 April 88
ADDRESS 1827 Tacoma St SIGNED SC Patterson

Completion of this form is required by 1521.05, Ohio Revised Code - file within 30 days after completion.

WHITE ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224 / Blue - Customer's Copy / Pink - Driller's Copy / Green - Local Health Dept. Copy