WELL LOG AND DRILLING REPORT

671364

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

NO CARBON PAPER NECESSARY– SELF-TRANSCRIBING

Permit Number WSN-88-109

COUNTY Montgomery TOWNSHIP Mad River SECTION OF TOWNSHIP

OWNER Nick R Gadon ADDRESS 1079 Georgia Rd. Circleville Oh. 43113

LOCATION OF PROPERTY 3219 Old Troy Pike

CONSTRUCTION DETAILS

Casing diameter 5 5/8 Length of casing 121

Type of screen Length of screen

Type of pump

Capacity of pump 10

Depth of pump setting 118

Date of completion 8 July 88
Rotary ☐ or Cable ☑

BAILING OR PUMPING TEST
(specify one by circling)

Test rate 10 gpm Duration of test 1 hrs

Drawdown 6 ft Date 8 July 88

Static level (depth to water) 80 ft

Quality (clear, cloudy, taste, odor) Clear

Pump installed by S C Patterson

WELL LOG*

Formations: sandstone, shale, limestone, gravel, clay	From	To
Top Soil	0 ft	2 ft
Clay	2	9
Dry Sand & Gravel	9	80
Sand & Gravel	80	121
5446		

SKETCH SHOWING LOCATION

Locate in reference to numbered state highways, street intersections, county roads, etc.



* If additional space is needed to complete well log, use next consecutively numbered form.

DNR 7802

DRILLING FIRM Patterson well Co REGISTRATION NUMBER 184 DATE 17 July 88

ADDRESS 1827 Tacoma St SIGNED S C Patterson

Completion of this form is required by 1521.05, Ohio Revised Code - file within 30 days after completion.

WHITE ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224 / Blue - Customer's Copy / Pink - Driller's Copy / Green - Local Health Dept. Copy

S-552